### Alaska Scientific Crime Detection Laboratory

# DataMaster Close Out Form Effective: 11/10/2021

Instrument #: 100423  Date: 6/19/24 Analyst: C. O'Bryant
Reason for Instrument Close Out
Unable to perform repairs at Intox.
Unable to perform repairs at Intox.  Ft. Wainwright approved close out.
State of Alaska Property ID#: Not owned by SoA.

Additional paperwork (page 2 and page 3) were found in the dry gas compartment of the instrument after returning from Intoximeter. COB 2024.06.19

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor

Version: 2.0

## Status Record Summary

Test Date	Test Time	Test Type		Status Message
/20/2020	20:18:08	Breath Record	RFI DETECTED	1
/20/2020 /20/2020	20:22:03	Breath Record	RFI DETECTED Maximum Attempts Exceeded	V2.4
23/2020	20:48:47 15:59:32	Breath Record Breath Record	Interference Detected	agr .
23/2020	16:04:48	Breath Record	Interference Detected	- 0(
01/2020	02:24:24	Breath Record	RFI DETECTED	Leak test  210 psi 1/24 2:55 p  214 psi 1/25 7:00 a  Filter wheel test 30/0
01/2020	02:26:34	Breath Record	Ambient Fall	LEAK test
05/2020	03:49:40	Breath Record	Maximum Attempts Exceeded	
30/2021	03:45:27	Breath Record	RFI DETECTED	- 1/24 2.55 P
30/2021	03:48:36	Breath Record Breath Record	RFI DETECTED Maximum Attempts Exceeded	- 210 DS1
05/2021 05/2021	21:44:29	Breath Record	Maximum Attempts Exceeded	1/25 7:000
15/2021	05:23:33	Breath Record	Maximum Attempts Exceeded	214 psi
04/2021	21:07:42	Breath Record	Pump Error	
05/2021	08:05:24	Breath Record	Pump Error	Fill 11 at 1 + 1 30/0
30/2021	09:38:13	Breath Record	Maximum Attempts Exceeded	Filter whoch test
30/2021	11:12:11	Breath Record	RFI DETECTED Simulator Timed Out	
14/2021 14/2021	05:13:51 05:19:21	Breath Record Breath Record	Standard Out of Range	
14/2021	05:24:03	Breath Record	Ambient Fail	
02/2022	07:38:49	Breath Record	Maximum Attempts Exceeded	
22/2022	02:32:02	Breath Record	Pump Error	
27/2022	02:42:56	Breath Record	RFI DETECTED	
29/2022	22:16:10	Breath Record	Internal Standard Error	
29/2022	22:21:09	Breath Record	RFI DETECTED Pump Error	
06/2022 13/2022	05:54:19	Breath Record Breath Record	Pump Error	
10/2022	05:40:37	Breath Record	Maximum Attempts Exceeded	<del>-</del>
10/2022	05:47:41	Breath Record	Maximum Attempts Exceeded	
19/2022	03:20:04	Breath Record	Maximum Attempts Exceeded	
26/2022	01:56:39	Breath Record	Interference Detected	AND AND CAPE
26/2022	02:02:43	Breath Record	Interference Detected	L #2,21 a # 42
26/2022	03:54:02	Breath Record	Interference Detected	- 0 A
15/2022 18/2022	08:04:53 12:07:50	Breath Record VOC Record	Pump Error Interference Detected	B 80
01/2022	23:11:01	Breath Record	Maximum Attempts Exceeded	
01/2022	23:17:52	Breath Record	Maximum Attempts Exceeded	<b>C</b> 1.73
18/2022	05:38:34	Breath Record	RFI DETECTED	t
24/2022	03:08:22	Breath Record	Blank Error	ch 525
02/2022	04:01:49	Breath Record	Interference Detected	Det0.045 1/25 9:0
06/2022	03:00:26	Breath Record	Maximum Attempts Exceeded Detector Overflow	Det -0.045
01/2023	02:40:05	Breath Record Breath Record	Detector Cverflow	-0,019
01/2023	02:59:28	Breath Record	Ambient Fail	-0,014
01/2023	03:01:33	Breath Record	Ambient Fail	
01/2023	05:35:05	Breath Record	Ambient Fail	
/01/2023	07:44:08	Breath Record	Ambient Fail	
01/2023	23:43:51	Breath Record	Ambient Fail	
03/2023	00:38:43	Breath Record	Ambient Fail Gas Flow Error	
/03/2023 /03/2023	09:18:01 10:12:36	Breath Record Breath Record	Standard Out of Range	
03/2023	10:16:01	Breath Record	Standard Out of Range	
17/2023	11:18:17	VOC Record	Standard Out of Range	
17/2023	12:00:33	VOC Record	Standard Out of Range	
/14/2023	12:57:05	Breath Record	Blank Error	-
/27/2023	09:01:49	Breath Record	Blank Error	
/25/2023	15:47:49	Supervisor Record Supervisor Record	Blank Error Blank Error	
/25/2023 /14/2023	16:13:36 10:53:56	Calibration Record	Blank Error	
14/2023	10:57:35	Calibration Record	Blank Error	
/14/2023	11:12:48	Calibration Record	Blank Error	
14/2023	11:36:55	Calibration Record	Blank Error	
/03/2023	14:36:39	VOC Record	Diagnostic Check Failed	
/03/2023	15:41:53	Calibration Record	Filter 3 Won't Zero	
/03/2023	15:51:27	Calibration Record	Diagnostic Check Failed	1011
/04/2023	16:05:54	VOC Record	Diaduogete cueck tailed	12'00
				1
		-		1/24
				,
				12:00
				0048
				- 0,0 1 9
				V29 -
				The Prince of the Control of the Con
				1/24

Seq	Inspection Task	Measurement Type
	900 Barometer CE#	Numeric
	910 Tank Lot #	Freeform
	915 Tank Cylinder #	Freeform
	930 Simulator 1 CE#	Numeric
	935 Solution 1 Lot #	Freeform
	938 Solution 1 Bottle #	Numeric
	940 Simulator 2 CE#	Numeric
	945 Solution 2 Lot#	Freeform
	950 Solution 2 Bottle #	Numeric
	1,020 DMT Incoming Software ID 43402	Freeform
	1,022 DMT Incoming Software DMT 3.02	Numeric
	1,024 DMT Incoming Software PIC 3.d3	Numeric
	1,025 DMT Incoming Software DMT Utils 2.4	Numeric
	1,026 DMT Incoming Software Network Utils —	Numeric
	1,027 DMT Incoming Software Modem	Numeric
	1,028 DMT Incoming Software Reports	Numeric
	1,030 DMT Incoming Software Question 2.2	Numeric
	1,031 DMT incoming Lamp 2,24	Numeric
	1,032 DMT incoming Bias 80	Numeric
	1,033 DMT incoming Cooler 1,76	Numeric
	1,034 DMT incoming Chopper 535	Numeric
	1,035 DMT incoming Detector -0.259	Numeric
	1,037 DMT incoming pump on Det ~0.263	Numeric
	1,038 DMT incoming pump off Det-0.259	Numeric
	1,040 Reference Barometer-Ambient 29,3	Numeric
	1,042 Unit Barometer-Ambient 29.4 in	Numeric
1	1,045 DMT Adjust Barometer	YesNo
Maci	1,053 DMT incoming Xq 0.102	Numeric
	1,054 DMT incoming Xq % \$\text{\$\text{\$\gamma}\gamma}\text{\$\gamma}\text	Numeric
	1,055 Incoming Acc Check TARGET —	Numeric
	1,060 Incoming Acc Checks (res1)	Numeric
	1,065 Incoming Acc Check ( res 2)	Numeric
	1,070 Incoming Acc Check (res 3)	Numeric
	1,100 DMT cleaned optics	Yes��ớ
	1,110 DMT adj filter wheel motor	YeaNo
	1,190 Update Software	Ye <b>s</b> No
	1,191 DMT Outgoing Software ID	Freeform
	1,192 DMT Outgoing Software DMT	Numeric
	1,194 DMT Outgoing Software PIC	Numeric
	1,195 DMT Outgoing Software DMT Utils	Numeric
	1,196 DMT Outgoing Software Network Utils	Numeric
	1,197 DMT Outgoing Software Modem	Numeric
	1,198 DMT Outgoing Software Reports	Numeric
	1,199 DMT Outgoing Software Question	Numeric
	1,200 Dry Gas leak test (He)	P/F/na
	1,220 Calibration Adjustment, value	Numeric

#### O'Bryant, Colleen S (DPS)

From: Julayha, Sazahan CIV USARMY IMCOM PACIFIC (USA) <sazahan.julayha.civ@army.mil>

**Sent:** Tuesday, June 18, 2024 11:50 AM

**To:** O'Bryant, Colleen S (DPS)

**Subject:** RE: DMT 100423

**Approved** 

Respectfully,

LT Sazahan Julayha Watch Commander Fort Wainwright Police Department 3025 Montgomery Road USAG Fort Wainwright, AK 99703

Office: 907-353-7702 Duty Cell: 907-370-9342

Email: sazahan.julayha.civ@army.mil

From: O'Bryant, Colleen S (DPS) <colleen.obryant@alaska.gov>

Sent: Tuesday, June 18, 2024 11:39 AM

To: Julayha, Sazahan CIV USARMY IMCOM PACIFIC (USA) <sazahan.julayha.civ@army.mil>

Subject: FW: DMT 100423

For documentation purposes could I get you to respond "Approved" if you agree with the following statements?

DataMaster DMT serial number 100423, owned by Ft. Wainwright, will be decommissioned and parted out leaving it no longer usable for forensic testing.

Colleen O'Bryant

Forensic Scientist III - Chemistry Alaska Scientific Crime Detection Laboratory 4805 Dr. Martin Luther King Jr. Ave Anchorage, Alaska 99507

907-269-5783 (direct) 907-350-2111 (cell)

From: Julayha, Sazahan CIV USARMY IMCOM PACIFIC (USA) <sazahan.julayha.civ@army.mil>

Sent: Tuesday, June 18, 2024 10:05 AM

To: O'Bryant, Colleen S (DPS) <colleen.obryant@alaska.gov>

Subject: RE: DMT 100423

From: O'Bryant, Colleen S (DPS) Sent: Tuesday, May 7, 2024 7:58 AM

To: Julayha, Sazahan CIV USARMY IMCOM PACIFIC (USA) <sazahan.julayha.civ@army.mil>

Cc: Walton, Derek J (DPS) <derek.walton@alaska.gov>

Subject: RE: DMT 100423

Derek approved the loaner staying for at least 6 months as we are looking into replacing the fleet of instruments. Funding is currently in the governor's budget but could easily be slashed by July 1 and we'd need to go an alternative route. If/when we replace the instruments, we'll have specifications for the instrument your agency needs to purchase to continue participating in the Statewide Breath Alcohol Program.

Let me know if you have any questions.

Colleen O'Bryant

Forensic Scientist III - Chemistry Alaska Scientific Crime Detection Laboratory 4805 Dr. Martin Luther King Jr. Ave Anchorage, Alaska 99507

907-269-5783 (direct) 907-350-2111 (cell)

From: Julayha, Sazahan CIV USARMY IMCOM PACIFIC (USA) <sazahan.julayha.civ@army.mil>

Sent: Monday, May 6, 2024 4:01 PM

To: O'Bryant, Colleen S (DPS) <colleen.obryant@alaska.gov>

Subject: RE: DMT 100423

Hello,

Per our Chief of Police, we won't be needing the instrument back. Will we be able to continue to use the loaner instrument long term?

Respectfully,

LT Sazahan Julayha Watch Commander Fort Wainwright Police Department 3025 Montgomery Road USAG Fort Wainwright, AK 99703

Office: 907-353-7702 Duty Cell: 907-370-9342

Email: sazahan.julayha.civ@army.mil

From: O'Bryant, Colleen S (DPS) < colleen.obryant@alaska.gov >

Sent: Monday, May 6, 2024 2:56 PM

To: Julayha, Sazahan CIV USARMY IMCOM PACIFIC (USA) < <a href="mailto:sazahan.julayha.civ@army.mil">sazahan.julayha.civ@army.mil</a>>

Cc: Walton, Derek J (DPS) < <a href="mailto:derek.walton@alaska.gov">derek.walton@alaska.gov</a>>

Subject: FW: DMT 100423

#### Lt. Julayha,,

I've got some bad news about your agency owned DataMater DMT (100423). Looks like we reached the point where the cost to repair the instrument exceeds the worth of the instrument. The history of this instrument was that it was suspected that a subject spit into the breath hose. The lab has chosen to close this instrument out as we'd do with state owned instruments that reach this point. You are currently utilizing a loaned instrument and may continue to do so. The instrument will be returned to the Alaska lab, would you like it returned to you following a close out procedure at the lab?

#### Colleen O'Bryant

Forensic Scientist III - Chemistry Alaska Scientific Crime Detection Laboratory 4805 Dr. Martin Luther King Jr. Ave Anchorage, Alaska 99507

907-269-5783 (direct) 907-350-2111 (cell)

From: John Holzer < <u>JHolzer@intox.com</u>> Sent: Monday, May 6, 2024 7:45 AM

To: O'Bryant, Colleen S (DPS) < colleen.obryant@alaska.gov>

Cc: Jason Peterson < JPeterson@intox.com>

Subject: DMT 100423

You don't often get email from <a href="mailto:iholzer@intox.com">iholzer@intox.com</a>. <a href="mailto:Learn why this is important">Learn why this is important</a>

**CAUTION:** This email originated from outside the State of Alaska mail system. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Ms. OBryant,

My name is John Holzer, and I am the technician at Intoximeters who is servicing several of your instruments. A few have been successfully repaired, and passed our QC process already. Unfortunately, I have an instrument now, serial #100423, SRO-060462, which may not be worth further attention. We have replaced the IR detector, the five-way valve with solenoid, and the phoenix connector on the control board for the detector. The instrument has improved, but still demonstrates *very* excessive instability during any testing, or even impacts to the work surface it is sitting on.

As it stands, we have replaced about \$1000 worth of parts, and over the 8 hour cap on labor (another \$900). It is the opinion of myself and the other technicians that repair of this instrument would require a new SBC, control board, and sample chamber, at the least. You have sent us a pair of SBCs, one of which was used to repair another instrument, so that wouldn't be an issue (assuming the remaining SBC works). The control board and sample chamber, however, would cost nearly another \$2000 and we can't promise these parts would solve the problems. It may also need a new

lamp, or any number of other things. Worst case scenario, we put a small fortune in to the instrument, ship it back, and it fails a month later.

Our theory (which I admit we cannot confirm), is that a contaminant of some kind got in to the instrument and corroded some, if not many, of the components. At this point, I can't advise continuing to try to repair this instrument. It just doesn't seem a good use of resources. Those resources aren't mine, however, so it is your call how we proceed.

We can, of course, keep replacing components, or we can remove the new components already installed and ship it back unrepaired. It is your decision, I just didn't feel like I should keep going on this without checking in and getting you up to speed.

Than you, and let me know what you want us to do. JOHNNY HOLZER

**Technical Services Department** 



●2081 Craig Road St. Louis, MO 63146●

**(314) 447-4729**