

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 6/11/2014
Effective: 6/11/2014

Version: CIISF 2014 R0
Status: Active

Date: 05/19/2017 Instrument Serial Number: 100402

Instrument Location: 6040 DEHAVILLAND AVE, ANC AK 99502

Supervisor Name and Agency: ARWIN YABUT ANC AIRPORT POLICE & FIRE

Describe the Status Change or Issue with the Instrument:

ISSUES CAME UP ON 5/19/17 WITH NO READING OF FLOW RATE.
IT WAS NOT ABLE TO RECEIVE SUBJECT SAMPLE.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 05/19/2017 1540hrs

For Use by SCDL

Additional Notes

Contacted Arwin on 5/19/17 after the second email
was received (see attached) and notified him
we were going to replace his instrument due to the
problems they had experienced earlier.
BMB 5/21/17

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740

Barnett, Brandi M (DPS)

From: DPS SCDL Toxicology (DPS sponsored)
Sent: Friday, May 19, 2017 2:34 PM
To: Barnett, Brandi M (DPS); Foster, Charles R (DPS); O'Bryant, Colleen S (DPS)
Subject: FW: DataMaster Instrument

From: Yabut, Arwin A (DOT)
Sent: Friday, May 19, 2017 8:59 AM
To: DPS SCDL Toxicology (DPS sponsored)
Cc: Westlake, Derrick M (DOT); Farmer, Michael A (DOT); Holler, Douglas W (DOT)
Subject: RE: DataMaster Instrument

Good Morning Toxicology Staff,
After re-booting the system this morning and conducting a VOC. The DataMaster is working as normal. I also tightened the connection on the back. I completed two tests and both times the DataMaster was operational as normal and reading air flow just fine. No further assistance needed.

Thanks
Officer Yabut
Anchorage Airport Police & Fire

From: Yabut, Arwin A (DOT)
Sent: Thursday, May 18, 2017 4:18 PM
To: DPS SCDL Toxicology (DPS sponsored)
Cc: Westlake, Derrick M (DOT); Farmer, Michael A (DOT); Holler, Douglas W (DOT)
Subject: DataMaster Instrument

Good Evening Toxicology Staff,
Our DataMaster DMT is out of service at this time. It is currently not reading air flow when administering a sample test. Our latest sample provided on 05/06/2017 1133hrs was graphed with an alcohol line, however, there was no Flow Rate. We recently tested the instrument today and it would not register any breath provided by our officer. I assume it may be the tube but not sure. Please advice what you would like us to do?
Officer Yabut
Anchorage Airport Police & Fire