

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 6/11/2014
Effective: 6/11/2014

Version: CIISF 2014 R0
Status: Active

Date: 3-1-17 Instrument Serial Number: 100386

Instrument Location: UAF POLICE DEPT, 612 YUKON DRIVE, FAIRBANKS, AK

Supervisor Name and Agency: SAM BEAUDREAU, UAF POLICE DEPT.

Describe the Status Change or Issue with the Instrument:

INSTRUMENT WILL NOT ACCEPT A BREATH SAMPLE.
" " " PERFORM A VOC.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 3-1-17, 23:10

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740

FW: UAFPD DataMaster is 10-7

DPS SCDL Toxicology (DPS sponsored)

Sent: Thursday, February 23, 2017 6:15 AM

To: O'Bryant, Colleen S (DPS); Foster, Charles R (DPS)

From: Samuel Beaudreault [sabeaudreault@alaska.edu]**Sent:** Wednesday, February 22, 2017 8:59 PM**To:** DPS SCDL Toxicology (DPS sponsored)**Subject:** Fwd: UAFPD DataMaster is 10-7

I was off for a few days and Officer Faris reports a problem with our Datamaster.
I did a test just now also, and got the same results.

The only thing wrong that I found was a plug was loose. It is the one that attaches the wires from the breath hose to the back of the machine.

I tightened it up and now it just beeps when the run button is pushed.

Turning it on and off a few times did not change anything.

I disconnected the breath hose from the machine and there is no blockage.

My shift this week is 8pm to 8am tonight, Thursday, and Friday nights, if you need to reach me directly at (907)474-7721.

Please let me know if I might be able to do something to fix it from here.

Thank you!

----- Forwarded message -----

From: Clay Faris <rfaris2@alaska.edu>

Date: Mon, Feb 20, 2017 at 9:23 PM

Subject: UAFPD DataMaster is 10-7

To: "UAF-Police-Dept@alaska.edu" <UAF-Police-Dept@alaska.edu>

FYI. DataMaster is currently 10-7. Sam, please get with the Crime Lab ASAP and get it back into service. I'm not a supervisor any longer, but I suspect the issue is with the breath hose. There is no resistance at all when providing a sample, and the machine doesn't register/recognize when breath is being blown (i.e. - it keeps beeping, instead of changing to a steady tone).

We did a mock DUI tonight as part of Cameron's training, and discovered the issue when our test subject attempted to provide a sample.

In the meantime, we'll need to plan on utilizing Airport PD or AST for DataMaster.

--
Officer Clay Faris
University Police Department
612 Yukon Drive, UAF Campus

Fairbanks, AK 99775
(907) 474-7721
rfaris2@alaska.edu

--
Officer Sam Beaudreault
UAF Police Department
ph. (907)474-7721
fax (907)474-5555

O'Bryant, Colleen S (DPS)

From: O'Bryant, Colleen S (DPS)
Sent: Friday, February 24, 2017 2:42 PM
To: 'Samuel Beaudreault'
Cc: Roth-Frey, Nicolette A (DPS)
Subject: RE: Datamaster

Sam, looks like your 5-way valve is stuck halfway between 'on and off'. We are going to send you a replacement instrument. Please take this one out of service and utilize another instrument until you get your new one.

**Nikki,
Please send UAF PD a replacement instrument.
Thanks,
Colleen**

From: Samuel Beaudreault [<mailto:sabeaudreault@alaska.edu>]
Sent: Thursday, February 23, 2017 9:39 PM
To: O'Bryant, Colleen S (DPS)
Subject: Re: Datamaster

Here are some photos of the 5 way valve.
Let me know if it did not cover what you need.

On Thu, Feb 23, 2017 at 10:03 AM, O'Bryant, Colleen S (DPS) <colleen.obryant@alaska.gov> wrote:

Sam,

Could you open the datamaster cover and take a picture of the 5-way valve?

I think it might be stuck.

From: DPS SCDL Toxicology (DPS sponsored)
Sent: Thursday, February 23, 2017 6:16 AM
To: Foster, Charles R (DPS); O'Bryant, Colleen S (DPS)
Subject: FW: Datamaster

From: Samuel Beaudreault [sabeaudreault@alaska.edu]
Sent: Wednesday, February 22, 2017 9:18 PM
To: DPS SCDL Toxicology (DPS sponsored)
Subject: Datamaster

I tried a couple more times to run tests on our broken Datamaster.
I got an Interference status message and one for Blank error.

The back was not blocked and I was the only one nearby, so I don't think I caused any of it.

Weird.

--

Officer Sam Beaudreault
UAF Police Department

ph. [\(907\)474-7721](tel:(907)474-7721)

fax [\(907\)474-5555](tel:(907)474-5555)

--

Officer Sam Beaudreault
UAF Police Department
ph. (907)474-7721
fax (907)474-5555

