

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 6.0

Effective: 1/17/2024

Date: 3/29/2024

Instrument #: 100669

Instrument Location: Palmer PD

Supervisor Name and Agency: Sgt. Luke Szipszky, Palmer PD

Describe the Status Change or Issue with the Instrument:

I was informed a trooper had pulled the heated breath hose sheath off the tube itself on the back of the instrument where it connects with the Datamaster itself. When I was sent a picture, it was about ½" of exposed tubing. I had an officer push the black covering back down to its original spot, completely covering the exposed breath tube. Ofc. White conducted a non-drinking subject test, and twice it showed "interference detected". There was also an RFI, but Ofc. White had key'd his mic on accident. I instructed Ofc. White to "perform a tank change" using the same tank. It then passed the following VOC and a non-drinking subject test. The instrument was never removed from service during the trouble shooting exercise and remains in service as of 3/29/24.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: Click or tap here to enter text.

Out of Service Date/Time: Click or tap here to enter text.

For Use by SCDL

Additional Notes

Click or tap here to enter text.

Email completed form to dps.scdl.toxicology@alaska.gov.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor