

In-Field Instrument Review (12/13/2014 – 1/3/2015)

100411 (Kenai PD)

From 12/13/14 to 1/3/15: 2 tank interference detected and 1 internal standard error.

From 9/8/14 to 1/16/15: 9 tank interference detected.

On 1/23/2015, Todd Hamilton was contacted and a replacement DMT was sent to his agency.

100686 (AST Aniak)

From 12/13/14 to 1/3/15: 2 internal standard errors.

Trooper Bower had contacted the breath alcohol section on 12/23/14 regarding internal standard errors. He was told to take this instrument out of service prior to this In-Field instrument review.







