

# Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 12/15/2017  
Effective: 12/15/2017

Version: CIISF 2017 R0  
Status: Active

Date: \_\_\_\_\_ Instrument Serial Number: \_\_\_\_\_

Instrument Location: \_\_\_\_\_

Supervisor Name and Agency: \_\_\_\_\_

Describe the Status Change or Issue with the Instrument:

---

---

---

---

---

---

---

---

---

---

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: \_\_\_\_\_

Out of Service Date/Time: \_\_\_\_\_

-----  
**For Use by SCDL**

**Additional Notes**

---

---

---

---

---

---

---

---

---

---

**Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)**

For questions contact the Breath Alcohol Program at 907-269-5740

## **O'Bryant, Colleen S (DPS)**

---

**From:** DPS SCDL Toxicology (DPS sponsored)  
**Sent:** Monday, August 3, 2020 8:30 AM  
**To:** Bozman, David W (DPS)  
**Subject:** RE: Fairbanks AST Datamaster issue #100378

**Trooper Bozman,**

**Based on the attached tests it looks as though the 5 way valve may not have opened/closed entirely. The black line indicates alcohol absorbance while the dashed line is flow. I don't see a flow line on the graph indicating the instrument was registering it. Your non-drinking subject test indicates a flow line (lacking alcohol as expected). The 5 way valve opens and closes multiple times throughout the testing procedure. It's possible it wasn't properly opening/closing during the subject test and was able to correct itself for yours.**

**Please let me know if you encounter any additional issues.**

**Colleen**

---

**From:** Bozman, David W (DPS) <david.bozman@alaska.gov>  
**Sent:** Wednesday, July 29, 2020 3:05 PM  
**To:** DPS SCDL Toxicology (DPS sponsored) <dps.scdl.toxicology@alaska.gov>  
**Subject:** Fairbanks AST Datamaster issue #100378

Good Afternoon,

Trp. Wolff told me about an issue he had while a subject was providing a sample. He reported the flow would not register and it resulted in an incomplete for the subject. The subject was able to provide a sample at FPD's Datamaster. I conducted a test on the Datamaster and it received the breath without any issues. I'm not sure if this is an operator/subject issue or an instrument issue. I wanted to let you know. I have attached the printouts from Trp. Wolff's subject and my test run. Please let me know if you require any further information.

Trooper David Bozman  
Fairbanks Patrol  
"D" Detachment  
1979 Peger Road  
Fairbanks, AK99709  
Office: (907)-451-5100  
Cell: (907)-953-8015  
Fax: (907)451-5165

SUBJECT TEST

Alaska Department of Public Safety  
DATAMASTER dmt: 100378

Date: 07/29/2020  
Time: 04:49:26

SUBJECT NAME:


LICENSE #:

OPERATOR NAME:  
TIMOTHY J WOLFF  
OPERATOR'S #: 8150

DEPT/AGENCY:  
AST  
CASE/REPORT:  
TEST TYPE: DUI

EXTERNAL STANDARD INFORMATION  
NOMINAL: 0.080  
TARGET AT 29.62: 0.079  
LOT #: AG923401  
EXPIRATION: 08/22/2021

DIAGNOSTIC CHECK	PASSED	04:50
BLANK TEST	0.000	04:50
INTERNAL STANDARD	VERIFIED	04:50
EXTERNAL STANDARD	0.079	04:50
BLANK TEST	0.000	04:51
SUBJECT SAMPLE	INCOMPLETE	04:53



SUBJECT TEST

Alaska Department of Public Safety  
DATAMASTER dmt: 100378

Date: 07/29/2020  
Time: 13:39:12

SUBJECT NAME:  
TEST TEST  
LICENSE #: 9073

OPERATOR NAME:  
DAVID W BOZMAN  
OPERATOR'S #: 9073

DEPT/AGENCY:  
AST  
CASE/REPORT: TEST  
TEST TYPE: TEST

EXTERNAL STANDARD INFORMATION  
NOMINAL: 0.080  
TARGET AT 29.59: 0.079  
LOT #: AG923401  
EXPIRATION: 08/22/2021

DIAGNOSTIC CHECK	PASSED	13:40
BLANK TEST	0.000	13:40
INTERNAL STANDARD	VERIFIED	13:40
EXTERNAL STANDARD	0.078	13:40
BLANK TEST	0.000	13:41
SUBJECT SAMPLE (Vol=5.33L)	0.000	13:42
BLANK TEST	0.000	13:42
EXTERNAL STANDARD	0.078	13:43
BLANK TEST	0.000	13:44

DW 3 <

