

In Field Instrument Review 7/18/2015-9/5/2015

100351 Anchorage Police Department 2 detector overflow and 1 filter won't zero

After looking into the instances they all occurred within a few days of one another and no problems have been seen since. The detector voltage was normal. It was decided to watch for future problems.

100359 Dillingham PD 6 Standard Out of Range Status Messages

The tank was changed on 8/28 and no problems have been noted since.

100364 Anchorage Airport Police

Removed from service for preventative maintenance.

100365 Kotzebue PD 2 Internal Standard Errors and misc. software errors

Removed from service 9/11.

100370 Homer PD Gas Flow Error

Tank was changed on 8/25 and no further problems have been seen.

100373 Seward PD

Removed from service 8/28 for preventative maintenance.

100665 St. Mary 2 Standard out of Range Status Messages

Tank was changed on 8/26. No further problems noted.

100666 King Cove misc. software errors

Removed from service 9/14.

100677 Bethel PD 2 Standard out of Range Status Messages

Emailed with request to change tank as it appears to be due to tank decline.

100685 UAA PD

Removed from service for preventative maintenance.

100688 AST Soldotna Tank Interference, Blank Error, Internal Standard Error

Appears to possibly be due to environmental or subject factors as surrounding internal standard readings look fine. Will watch for next time.

100696 Hooper Bay Interference Detected on External Standard and IS Error

Removed from service 9/10.



