

In Field Instrument Review 4/11/2015-5/30/2015

100343 Petersburg PD: 1 Internal Standard Error-several tests after with no error and the internal standard value is well within the passing tolerance on these tests. No action taken.

100347 Tok: 2 Standard out of Range Status Messages- Tank change done of 6/1 and instrument reading well within tolerance. No action taken.

100365 Kotzebue: 4 Standard out of Range Status Messages- All 4 were on the same subject and the other subject tests looked to be well within range. No action taken.

100384 NSBPD: 3 internal standard errors- internal standard reading history is approaching the 4% tolerance. Instrument removed from service.

100423 Ft. Wainwright: 3 interference detected on subject sample- all on same subject. No action taken.

100421 JBER: Instrument removed from service prior to in field instrument review for internal standard error.

100691 Glacier Bay: Removed from service after VOC day when receiving detector overflow and freezing screen occurred. Instrument wouldn't upload in field.



