

**In Field Instrument Review**  
**Dates: 12/12/2018 – 01/03/2019**  
**Reviewed by Colleen O'Bryant**

100347 (Craig PD) – 2/5 – Gas Flow Error – Tank changed 12/24/2018 and check valve checked – Recommend Replacement  
100348 (Fort Wainwright) – 1/12 – Tank Interference – No action taken  
100356 (Skagway PD) – 1/2 – RFI – No action taken  
100369 (AST/Talkeetna) – 1/1 - RFI – No action taken  
100374 (APD) – 7/96 – RFI, Pump Error, Blank Error, Standard Out of Range, Ambient Fail – No action taken  
100378 (AST/Fairbanks) – 2/12 – RFI, Ambient Fail – No action taken  
100379 (Wasilla PD) – 2/17 - RFI – No action taken  
100403 (Metlakatla PD) – 1/4 – Pump Error – No action taken  
100405 (Dillingham PD) – 1/3 – Internal Standard Error (occurred on 12/12 – also noted on pervious In Field Instrument Review) – Followed by a completed test – Recommend Continued Monitoring  
100413 (Homer PD) – 2/5 – RFI – No action taken  
100415 (Sitka PD) – 3/10 – Pump Error, Blank Error, Static Analysis Error – Recommend Monitoring  
100416 (Fairbanks PD) 1/13 - RFI – No action taken  
100418 (Kenai PD) – 1/5 – Blank Error – No action taken  
100667 (AST/Mat-Su West) – 6/16 – RFI, Detector Overflow – Removed from service on 12/28/2018  
100668 (Palmer PD) – 1/14 – RFI – No action taken  
100678 (AST/Mat-Su West) – 1/5 – RFI – No action taken  
100679 (Haines PD) – 1/3 – Blank Error – No action taken  
100691 (Valdez PD) – 1/2 – Tank Interference - Followed by a completed test – No action taken  
100694 (APD) – 4/67 – Pump Error, Blank Error, Standard Out of Range – Followed by a completed test – No action taken  
100695 (JBER) – 3/8 – RFI, Ambient Fail – All occurred on the same subject and followed by a completed test – No action taken

\*\*Not included in this review were: 100377 AST/St. Mary's and UAA PD



