

In Field Instrument Review 07/18/2016 to 09/05/2016
Prepared by Colleen O'Bryant on 09/12/2016

100345 (AST/Soldotna) – RFI (4) – 4/23 tests – no action taken

100354 (Bristol Bay Borough PD) – Standard Out of Range (5) – 5/9 tests – tank change occurred on 07/26/2016

100355 (Seward PD) – RFI (1), Pump Error (1), Ambient Fail (1) – 3/20 tests – all occurred on the same subject and don't appear to be systemic – no action taken

100359 (Dillingham PD) – Standard Out of Range (2) – 2/9 tests – both occurred on the same subject with lot 01315080A2, exp 02/2017. Agency has newer lot, will advise to switch tanks.

100364 (Junuea PD) – Pump Error (1) – 1/80 tests – no action taken

100367 (Palmer PD) – RFI (1) – 1/24 tests – no action taken

100368 (AST/Willow) – Interference (3) – 3/4 tests – three tests on the same subject with a passing non-drinking subject test following – no action taken

100370 (Homer PD) - RFI (1) – 1/17 tests – no action taken

100376 (Metlakatla) – RFI (3), Pump error (1) – 4/16 tests – no action taken

100386 (UAF PD) – RFI (1) – 1/4 tests – no action taken

100387 (Fairbanks PD) – RFI (2) – 2/11 tests – no action taken

100389 (AST/Girdwood) – RFI (2) – 2/10 tests – no action taken

100396 (APD) – RFI (1), Pump Error (2) – 3/89 tests – no action taken

100403 (Denali National Park) – RFI (2), Ambient Fail (2) – 4/8 tests - all occurred on the same subject. No action taken

100404 (APD) – Gas Flow Error (1), Ambient Fail (1) – 2/25 – tank change occurred on 08/22/2016

100422 (JBER) – RFI (1), Interference (2) – 3/23 tests – no action taken

100423 (Ft. Wainwright MP) – RFI (1), Pump Error (1) – 2/13 tests – no action taken

100667 (Mat-Su West) – RFI (5), Interference (4) – 9/29 tests – see 100368 for details, same subject for interference tested 4 times. No action taken

100669 (Yakutat DPS) – RFI (1) – 1/2 tests - no action taken

100674 (Juneau PD) – Standard Out of Range (2) – 2/5 tests – tank change occurred on 08/17/2016

100684 (AST/Delta) – RFI (1), Blank Error (1) – 2/3 tests – both occurred on the same subject followed by an accepted sample. No action taken

100688 (Hooper Bay PD) – Internal Standard Error (1) – 1/5 tests – followed by two accepted samples. Reviewed all test data from 2016 and it does not appear to be a trend. Will monitor instrument

100700 (Soldotna PD) – RFI (1) – 1/13 tests– no action taken

*The following instruments were not included in the review as they were unable to be uploaded: 100344 (King Cove PD) and 100424 (Eielson AFB).

