

Alaska Scientific Crime Detection Laboratory

DataMaster Check In Form

Issued: 1/13/2017
Effective: 1/17/2017

Version: DMCIF 2017 R0
Status: Active

Instrument S/N 100358

Received From Intoximeters

Date 03/25/2021

Analyst Derck walton

1. Reason for instrument return:

Repaired for Fluv voltage registering on detector,
returbished by manufacturer

2. Change instrument and case location in JusticeTrax Breath Alcohol Database

3. Ensure change in instrument status form is in JusticeTrax

4. Upload

*Instrument was not in the field
DM 03/25/2021*

5. Update agency information and polling status in DM Host Calling Program

6. Check for VOCs

From Intoximeters

7. Intoximeters Repair Paperwork (attached)

SRO Number: SRO-044596

Received Date: 02/25/2021

Completion Date: 03/16/2021

SRO Type: REPAIR

SRO Description: DMT Repair/Preventive Maintenance

Customer ID: C000003651

Customer PO: 021221-Walton

Contact: Derek Walton

Email: derek.walton@alaska.gov

Ship To:

Alaska Department of Public Safety
Procurement & Supply Section
4805 Dr. MLK Jr. Avenue
Anchorage AK 99507

Units on SRO

1	LEGDMT	LEGACY DMT
---	--------	------------

Service Line: 1		**All Instruments are Calibrated to Factory Specifications**	
Unit Type:	(LEGDMT) LEGACY DMT		
Serial Number:	50100358		
Reason:	DMT Functional		
	Acc Fail		
Reason Notes:	Customer Reported Issue: Please repair for flow voltage registering on detector (when blowing, detector goes up, when breath stops, detector goes to zero).		
Resolution:	Replaced		
	RPL mech		
Resolution Notes:	Replaced air flow adjuster and discolored kinked tubing.		
Parts:	<u>Qty</u>	<u>Part Number</u>	<u>Part Description</u>
	1	90-8000-00	CONTRACT PREV MAINT DMT
Reason:	Preventive Maintenance		
	planned		
Reason Notes:	Preventive Maintenance		
Resolution:	Prev M		
	planned		
Resolution Notes:	Cleaned & adjusted filter wheel solenoid. Updated filter wheel solenoid mounting screws. Updated stepper motor adjustment lock down screw. Replaced filter wheel motor pinion. Cleaned, lubricated, & adjusted filter wheel moving parts. Removed, inspected, and applied metallic seal tape to mirror blocks of Sample Chamber. Replaced discolored kinked tubing and inspected 5-Way Valve. Installed TB-30 DMT Digital Pots Mod on Control Board. Optimized detector position. Adjusted Tech Screen settings.		
	1	59-0036-00	DMT HRDW CLIP BREATH TUBE HOLD 37058
	2	59-0085-00	DMT HRDW BASE RUBBER BUMPER 31360
	1	001199-00	DMT ELEC REGULATOR V LDO 3.3V OUT 30V IN
	1	59-0057-00	DMT HRDW FLOW CONTROL ASSY 41396

Order Packing Slip Report

Intoximeters
Experience · Service · Integrity

3/22/2021 2:34:55 PM

Packing Slip: 224186

Pack Date: 3/22/2021

SRO: SRO-044596



From: Intoximeters, Inc
2081 Craig Road
St Louis MO 63146
USA

Customer: C000003651

Ship To: 2

Alaska Department of Public Safety
4805 Dr MLK Jr Ave
Anchorage AK 99507
USA

Alaska Department of Public Safety
Procurement & Supply Section
4805 Dr. MLK Jr. Avenue
Anchorage AK 99507
USA

Customer PO: 021221-Walton

Ship Via: FDX

FED EX

Weight: 37.00

Delivery Terms : 2D

FOB : ORIGIN

Packages: 1

Customer Ship Account :

Line Number	Item	UM	Ordered Quantity	Shipment Quantity	Backorder Quantity
1	LEGDMT	LEGACY DMT			50100358
1	90-8000-00	EA		1.00	0.00
	CONTRACT PREV MAINT DMT				
2	59-0036-00	EA		1.00	0.00
	DMT HRDW CLIP BREATH TUBE HOLD 37058				
3	59-0085-00	EA		2.00	0.00
	DMT HRDW BASE RUBBER BUMPER 31360				
4	001199-00	EA		1.00	0.00
	DMT ELEC REGULATOR V LDO 3.3V OUT 30V IN				
5	59-0057-00	EA		1.00	0.00
	DMT HRDW FLOW CONTROL ASSY 41396				

Rec'd 03/23/21
JMV