

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Effective: 11/10/2021

Version: 2.0

Date: 12 May 2022 Instrument #: 100255

Instrument Location: Clear Space Force Station

Supervisor Name and Agency: Jones, Kevin 268th SFS

Describe the Status Change or Issue with the Instrument:

Datamaster placed Out of Service due to Filter Wheel Error. Error initiated during a Test sequence after starting Subject Test.

-Ran multiple Filter Wheel tests and each resulted in error's

-Reset the Datamaster DMT but same error persisted

-Went into Technician Mode to manually set a filter position and same error resulted *

-Performed a VOC that PASSED all portions

-Attempted an additional Filter Wheel test after passed VOC but still continued to have errors

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 05/12/2022 @1640 hours

For Use by SCDL

Additional Notes

* Kevin Jones indicated Technician mode allowed him to manually choose a filter position. Technician mode is a software option that allows the user to move one of the three filters or the internal standard (or a combination) into the path of the detector. This can be done for troubleshooting purposes. During a subject testing sequence, the filters move in the path of the detector as required by the software in all subject testing sequences. This sequence cannot be changed by Technician mode. COB 5/24/22

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740