

In Field Instrument Review for 10/24/2016 to 12/12/2016

Prepared by Brandi Barnett on 12/22/2016

100345 (AST Soldotna)- RFI 3/19: no action taken

100355 (Seward PD)- RFI 2/8: no action taken

100356 (Skagway PD)- RFI 1/7: no action taken

100357 (St. Paul PD)- RFI 3/4: All one subject-no action taken

100363 (Nome PD)- Blank Error 1/8, Pump Error 1/8: no action taken

100364 (APD)- 3/115 Interference, 2/115 Blank Error, 1/115 Ambient Fail: no action taken

100367 (Palmer PD)- 2/33 Pump Error, 2/33 Interference: Both interference same subject, no action taken.

100370 (Homer PD)- 1/13 Internal Standard Error: no action taken

100384 (Juneau PD)- 1/10 Pump Error: no action taken

100387 (Fairbanks PD)- 2/25 RFI: no action taken

100391 (Wrangell PD)- 1/11 interference, 3/11 Tank interference- old tank in use. Will send a new tank and monitor after new tank installed.

100396 (APD)- 2/104 interference, 1/104 blank error: no action taken

100397 (AST Fairbanks)- 1/25 RFI, 1/25 Tank Interference: no action taken

100398 (Kotzebue PD)- 1/4 RFI: no action taken

100404(APD)- 1/22 Pump error, 1/22 Blank Error, 1/22 Ambient Fail: no action taken

100406(Craig PD)-1/6 RFI- no action taken

100421(JBER)- 1/24 RFI, 1/24 Interference, 2/24 blank error, 1/24 internal standard error: no action taken

100423(Ft. Wainwright)- 1/13 pump error: no action taken

100424(Eielson AFB)- 3/5 RFI: all on one person, one test after, no action taken

100673 (NSBPD)-1/4 Static Analysis Error: 3 more static analysis errors after 12/12/2016. Instrument being removed from service.

100674(Juneau PD)- 1/8 RFI, 1/8 Pump error: no action taken

100681(Whittier PD)- 1/9 tank interference, 2/9 ambient fail, 2/9 detector overflow: detector overflow all on tests run as test, test. Likely training occurring.

100683(AST Glennallen)- 1/4 Standard Out of Range: no action taken

100684 (AST Delta Junction)- 1/6 RFI: no action taken

100690 (Sitka PD)- 1/21 Tank interference: no action taken

100691 (Valdez PD)- 2/15 interference, 2/15 blank error, 1/15 gas flow error: both interference same subject, both blank error same subject, no action taken

100695 (Wasilla PD)- 5/53 RFI: no action taken

100698 (Kenai PD)- 2/17 tank interference: no action taken



