

# Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 6/11/2014  
Effective: 6/11/2014

Version: CIISF 2014 R0  
Status: Active

Date: 2-23-17 Instrument Serial Number: 100404

Instrument Location: Anchorage Jail

Supervisor Name and Agency: D. Noll APP

Describe the Status Change or Issue with the Instrument:

Taken out of service per SCDL staff due  
to gas flow error

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: \_\_\_\_\_

Out of Service Date/Time: 2-23-2017 10545

For Use by SCDL	Additional Notes

Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)

For questions contact the Breath Alcohol Program at 907-269-5740

## O'Bryant, Colleen S (DPS)

---

**From:** O'Bryant, Colleen S (DPS)  
**Sent:** Tuesday, February 21, 2017 2:15 PM  
**To:** Noll, David M. (DNoll@muni.org)  
**Cc:** Foster, Charles R (DPS); brandi.barnett@alaska.gov; Roth-Frey, Nicolette A (DPS)  
**Subject:** RE: Datamaster DMT 100404

David,

It looks like 100404 started having gas flow errors on Saturday, February 18th, with two subject test attempts followed by two failed VOC attempts.

We'd like to give you a new instrument to place in service. Please remove 100404 from service.

When you bring back 100404 we will replace that instrument as well as give you a replacement for DMT #3 spot at AJ that is sitting vacant due to the damaged phone line.

Please remember to fill out the appropriate paperwork for all instruments (in and out of service).

Let me know if you have any questions.

Colleen

-----Original Message-----

**From:** DPS SCDL Toxicology (DPS sponsored)  
**Sent:** Tuesday, February 21, 2017 6:37 AM  
**To:** Foster, Charles R (DPS); O'Bryant, Colleen S (DPS); Barnett, Brandi M (DPS)  
**Subject:** FW: Datamaster DMT 100404

---

**From:** Noll, David M. [DNoll@muni.org]  
**Sent:** Saturday, February 18, 2017 8:46 AM  
**To:** DPS SCDL Toxicology (DPS sponsored)  
**Subject:** Datamaster DMT 100404

Good morning:

Datamaster 100404 has been giving repeated gas flow errors. I tried a fresh tank but while attempting the VOC, it still indicated a gas flow error and would not complete the VOC. Please advise what you want done with it.

Also, it appears the data port at the jail has been repaired, the one that had been ripped from the wall. If you are willing to bump us back up to 3 Datamasters I have high hopes that the DUI unit will put all of them to good use.

Thanks,  
Dave Noll