

**In Field Instrument Review 02/21/2017 – 04/21/2017**  
**Prepared by Colleen O'Bryant on 04/27/2017**

- 100345 (AST/Soldotna) – RFI 1/18 – no action taken
- 100347 (Craig PD) – RFI 2/7 – no action taken
- 100355 (Seward PD) – RFI 3/6 – two occurred on the same subject followed by a successful test, the other also followed by a successful test – no action taken
- 100358 (UAA PD) – 2/3 Interference, Blank Error – blank error occurred during testing – no action taken
- 100359 (Dillingham PD) – Tank Interference, Internal Standard Error and Static Analysis Error – 4/10 – instrument will be removed from service due to status messages
- 100361 (Unalaska PD) – RFI – 1/8 – no action taken
- 100364 (APD)– Interference, Blank Error, Diagnostic Failed, Filter Wheel Error – 7/137 – 3 messages occurred on the same subject, instrument will be monitored
- 100367 (Palmer PD ) – Standard out of range – 1/27 – no action taken
- 100386 (UAF PD) – Tank Interference, Blank Error – 2/3 – done on test/test, no action taken
- 100392 (Kodiak PD) – Pump Error – 1/9 – successful subject test obtained after – no action taken
- 100396 (APD) – RFI, Pump Error, Interference – 4/102 – no action taken
- 100421 (JBER) - Pump Error, Interference, Blank Error – 7/57 - all interference showed elevated filter 3 and were followed by a successful test, all blank errors were followed by a successful test, monitoring instrument
- 100669 (APD) – Interference – 7/31 – 4 subjects, filter 2 readings elevated, monitoring instrument
- 100674 (Juneau PD) – RFI – 1/10 – no action taken
- 100678 (AST/Anchor Point) – Tank Interference – 1/4 - successful subject test obtained after – no action taken
- 100679 (Haines PD) – Pump Error - 1/4 - successful subject test obtained after – no action taken
- 100680 (Sand Point PD) - Blank Error – 2/4 – one message on a test/test, the other on a subject test followed by a successful test, will monitor instrument.
- 100684 (AST/Delta) – RFI - 1/3 - successful subject test obtained after – no action taken
- 100690 (Sitka PD) – Tank Interference, Blank Error – 5/20 – instrument removed from service
- 100691 (Valdez PD) – Blank Error – 1/4 – no action taken
- 100695 (Wasilla PD) Interference Detected, Blank Error – 4/42 – all interference on the same subject, blood tested, no action taken
- 100698 (Kenai PD) – Pump Error, Tank Interference, Blank Error, Diagnostic Failed – 7/18 – diagnostic failed followed by successful test, interference and blank error occurred during test/test – no action taken

Data from the following instruments were not added to this review as the instruments were unable to upload at the time the review was created: Fairbanks Airport PD, Whittier PD at Girdwood location, and Sand Point PD.



