Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017 Effective: 12/15/2017 Version: CIISF 2017 R0 Status: Active

Date:	Instrument Serial Number: 100403
Instrument Location: MetItakatla	a PD
Supervisor Name and Agency	: Derek Walton - SCDL via e-mail with Bruce Janes - Metlakatla PD
Describe the Status Change of Three gas flow errors were observed on regulator which he did.	r Issue with the Instrument: the In Field Instrument Review for 7/19/19 to 9/5/19. Notified the supervisor to replace the o-ring on the
If instrument was placed in se In Service Date/Time: <u>NA</u>	rvice or removed from service, fill out the appropriate sections below.
Out of Service Date/Time: <u>NA</u>	
For Use by SCDL	Additional Notes
Email	completed form to <u>dps.scdl.toxicology@alaska.gov</u>
For question	ons contact the Breath Alcohol Program at 907-269-5740

Page 1 of 1 All printed copies are uncontrolled. Approved by Forensic Alcohol Supervisor

Walton, Derek J (DPS)

From:	Bruce Janes <bjanes@metlakatla.com></bjanes@metlakatla.com>
Sent:	Monday, September 30, 2019 9:01 AM
То:	Walton, Derek J (DPS)
Subject:	Re: Datamaster - Gas flow errors

I got it fixed

......

From: Walton, Derek J (DPS) <<u>derek.walton@alaska.gov</u>> Sent: Friday, September 27, 2019 3:31:53 PM To: Bruce Janes Subject: Datamaster - Gas flow errors

Hello sir,

Your Datamaster instrument has been experiencing gas flow errors. This may be related to the o-ring on the regulator cracking or breaking. Please replace the o-ring.

There should be new o-rings in a plastic zip bag taped to the interior of the black door to the tank compartment. Please let me know if you need any further instructions or assistance.

Thank you for your time and consideration,

Derek J. Walton

Forensic Scientist III – Chemistry Technical Lead – Seized Drugs State of Alaska Scientific Crime Detection Laboratory Phone: (907) 269-5628