

In Field Instrument Review 02/21/2018 – 04/11/2018

Prepared By: Derek Walton

Supervised by: Colleen O'Bryant

100352 (Anchorage Airport PD): 1/8 Pump error – no action taken  
100355 (Seward PD): 1/7 Standard Out of Range – Improved after tank change, No action taken  
100360 (AST Soldotna): 2/23 RFI, 2/23 Interference – No action taken  
100364 (APD Jail): 1/108 RFI, 1/108 Pump error, 2/108 Interference, 3/108 Standard Out of Range - 3 in a row on March 5<sup>th</sup> with old dry gas lot, 1 Undefined error (Code 32) – Blank before subject test – Recommend observation  
100370 (Juneau PD): 1/14 Gas Flow Error – No action taken  
100378 (AST Fairbanks): 10/62 RFI, 3/62 Interference Subject – RFI with different officers/dates, All interferences on 1 person – Contacted breath test supervisor on 4/26 to notify of high RFI. Supervisor indicated he would send a reminder to turn off radios in vicinity of instrument – Recommend observation  
100379 (Wasilla PD): 3/32 RFI – No action taken  
100402 (APD Jail): 1/109 RFI, 1/109 Pump error, 3/109 Interference Subject – 2 on same person, 1/109 Standard Out of Range – Same subject as 2/3 interferences – No action taken  
100406 (Palmer PD): 2/22 RFI, 1/22 Pump Error – No action taken  
100416 (Fairbanks PD): 1/39 RFI – No action taken  
100422 (JBER): 1/4 RFI – No action taken  
100666 (Bethel PD): 1/20 Blank error – No action taken  
100667 (AST Mat-Su West): 3/10 RFI – No action taken  
100670 (AST Bethel): 6/12 Standard Out of Range – All after subject test, All on old lot of dry gas. Tank changed 3/9 and again on 3/24 to new lot – No action taken  
100674 (Juneau PD): 2/11 RFI – No action taken  
100684 (AST Delta): 2/2 Internal Standard Error, Taken out of service on 3/1  
100685 (AST Tok): 1/8 RFI, 2/8 Interference Subject, 1/8 Internal Standard Error – All but RFI on 1 subject, 4 Interference on Dry Gas on 4/21 – Recommend observation  
100691 (Valdez PD): 1/11 RFI – No action taken  
100695 (JBER): 1/17 Pump Error – No action taken  
100696 (Soldotna PD): 2/10 Interference Subject – No action taken

Instruments out of service as of 3/25/18 due to expired tanks:

Ft. Yukon (100362), Eielson AFB (100424), Sand Point (100680), Hooper Bay (100682)

Instrument locations not included in In Field Review due to unable to upload:

Girdwood (100388), Metlakatla (100403), Whittier (100681)



