

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 09-17-2021 Instrument Serial Number: 100377

Instrument Location: AST St. Mary's post

Supervisor Name and Agency: Tatiana Lee - ASCDL

Describe the Status Change or Issue with the Instrument:

AST St. Mary's DMT did not populate a VOC on 09-05-2021. I called the post and spoke to Trooper Kenton Mayfield who advised me that Sgt. Eugene Fowler (who usually handles their agency's Datamaster is out for another month). He also confirmed that their Datamaster still had the expired tank installed. Trooper Mayfield is a current Breath Test Operator and I provided him with instructions on how to perform a tank change. The new tank was installed and a VOC was initiated and completed. I advised him to give their datamaster a restart after the VOC was completed. He emailed me a copy of the scanned VOC; however, was unable to upload a copy of the files into a USB. He was given an error that said he did not have high enough security clearance. The VOC files was succesfully uploaded in DMHost so he did not need to upload the files into a USB.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: _____

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740