

# Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 6/11/2014  
Effective: 6/11/2014

Version: CIISF 2014 R0  
Status: Active

Date: 12/13/17 Instrument Serial Number: 100347

Instrument Location: Craig PD

Supervisor Name and Agency: Charles Foster - SCDL

Describe the Status Change or Issue with the Instrument:

RS Ely (Craig PD) called me because the scheduled 12/12/17 VOC test sequence failed to complete due to a Gas Flow Error status message. I asked him to remove & reinstall the external dry gas tank and restart the VOC test. Another gas flow error occurred. I then asked him to reposition the double check valve so that it was resting upright. Another VOC test was started and no Gas Flow Errors occurred. I then told him to secure the double check valve to the inside wall of the DMT with double sided tape so that it couldn't fall over.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: N/A

Out of Service Date/Time: N/A

For Use by SCDL

Additional Notes

---

---

---

---

---

---

---

---

---

---

Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)

For questions contact the Breath Alcohol Program at 907-269-5740