

Alaska Scientific Crime Detection Laboratory

DataMaster Check In Form

Issued: 1/13/2017
Effective: 1/17/2017

Version: DMCIF 2017 R0
Status: Active

Instrument S/N 100399

Received From Intoximeters

Date 03/18/21

Analyst Derch Walton

1. Reason for instrument return:

Repaired for not uploading

2. Change instrument and case location in JusticeTrax Breath Alcohol Database

3. Ensure change in instrument status form is in JusticeTrax

4. Upload

*Instrument was not in the field
DMV 03/18/21*

5. Update agency information and polling status in DM Host Calling Program

6. Check for VOCs

From Intoximeters

7. Intoximeters Repair Paperwork (attached)

Order Packing Slip Report

Intoximeters
Experience · Service · Integrity

3/11/2021 12:15:13 PM

Packing Slip: 223355

Pack Date: 3/11/2021

SRO: SRO-044594



From: Intoximeters, Inc
2081 Craig Road
St Louis MO 63146
USA

Customer: C000003651

Ship To: 2

Alaska Department of Public Safety
4805 Dr MLK Jr Ave
Anchorage AK 99507
USA

Alaska Department of Public Safety
Procurement & Supply Section
4805 Dr. MLK Jr. Avenue
Anchorage AK 99507
USA

Customer PO: WTY03

Ship Via: FDX

FED EX

Weight: 37.00

Delivery Terms: GND

FOB: DESTINATION

Packages: 1

Customer Ship Account:

Line Number	Item	UM	Ordered Quantity	Shipment Quantity	Backorder Quantity
1	LEGDMT	LEGACY DMT			50100399
1	27-5865-00	EA	1.00		0.00

I/O MODEM ASSY HIGH SPEED

Rec'd 03/16/21
JM

SRO Number: SRO-044594

Received Date: 02/25/2021

Completion Date: 03/09/2021

SRO Type: REPAIR

SRO Description: DMT Repair

Customer ID: C000003651

Customer PO: WTY03

Contact: Derek Walton

Email: derek.walton@alaska.gov

Ship To:

Alaska Department of Public Safety
 Procurement & Supply Section
 4805 Dr. MLK Jr. Avenue
 Anchorage AK 99507

Units on SRO

1	LEGDMT	LEGACY DMT
---	--------	------------

Service Line: 1		**All Instruments are Calibrated to Factory Specifications**	
Unit Type:	(LEGDMT) LEGACY DMT		
Serial Number:	50100399		
Reason:	DMT Functional		
	No Comm		
Reason Notes:	Customer Reported Issue: Not uploading via the modem line.		
Resolution:	Replaced		
	RPL comp		
Resolution Notes:	Replaced bad Modem Module.		
Parts:	<u>Qty</u>	<u>Part Number</u>	<u>Part Description</u>
	1	27-5865-00	I/O MODEM ASSY HIGH SPEED