

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 6.0

Effective: 1/17/2024

Date: 5/20/2025

Instrument #: Click or tap here to enter text.

100255

Instrument Location: Click or tap here to enter text.

Clear SFS AK 99704

Supervisor Name and Agency: Click or tap here to enter text.

Tsgt William C Bailey 268 SFS

Describe the Status Change or Issue with the Instrument:

Click or tap here to enter text.

Detector overflow

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: Click or tap here to enter text.

Out of Service Date/Time: Click or tap here to enter text.

20 May 2025 0942

Instrument was never officially in service due to no passing VOC
CKG 5/20/2025

For Use by SCDL

Additional Notes

Click or tap here to enter text.

Spoke to William Bailey over the phone. The DataMaster owned by Clear AFB (100255) was returned to the agency. However, 100255 was displaying detector overflow status messages and was unable to be placed into service. William Bailey explained that troubleshooting occurred which included attempting numerous VOCs, and that the top of the DataMaster was opened to ensure that there were no loose connections or tubing. This was unable to be readily resolved in the field and will be returned to the crime lab. CKG 5/20/2025

Email completed form to dps.scdl.toxicology@alaska.gov.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor