

# Alaska Scientific Crime Detection Laboratory

## DataMaster Check In Form

Issued: 2/2/2015  
Effective: 2/2/2015

Version: DMCIF 2015 R0  
Status: Active

Instrument S/N 100367

Received From NPAS

Date 2/27/15

Analyst CRF

1. Reason for instrument return:

NPAS repair. Sent to NPAS due to detector  
voltage increase when exposed to RFI

2. Change instrument and case location in JusticeTrax Breath Alcohol Database

3. Ensure change in instrument status form is in JusticeTrax  N/A

4. Visual Inspection

5. Upload  N/A

6. Update agency information and polling status in DM Host Calling Program  N/A

7. Check for VOCs  N/A

From NPAS

8. NPAS Repair Paperwork (attached)

Work Ord No 49122

National Patent Analytical Systems, Inc.  
Service Action Report

Serial No 100367

Date 12/17/14

Customer Alaska Dept of Public

Phone 907-269-5582

Contact Bolz

War Exp 1/13/13

Mx Exp

Ship Damage?  Y  N

Cust Pick Up??  Y  N

Initial Comments: note any shipping damage or estimates required, along with accessories

SEE ATTACHED

Describe problem seen and/or attach documents received

see attached documents

Keyword

Finding

Error Code

Enter Hours

Repair Comments and work Performed

performed voltage checks, evaluated&verified regular operation of rfi, ran several accuracy tests.

Solution Lot No

Voltage Set Values In			Voltage Set Values Out		
Lamp	1.500	Brth Vol	1.550	Lamp	1.500
Meter	0.092	Filter Dif	.820	Meter	0.185
Stability	0.001			Stability	0.001

Part No	Qty Ord	Pick	Back Ordered	Total ship	Description	Price Ea
9DMT	1.0				DATAMASTER DMT SERVICE RETURN 100367	
NOTE	1.0				BREATH TUBE	
NOTE	1.0				NANUK CASE	
r500-1	1.0				Service Charge for Repair	119.000

Date Completed 1/16/15

Technician c.townsend

Pick up Signature

