DataMaster Evaluation Form

Issued: 7/10/2015 Effective: 7/10/2015

Version: DMEF2015 R0 Status: Active

Instrument # 100 345 Date: _7/23/15

Analyst: Brandi Barnett

1.	Reason for instrument evaluation
	Instrument sample chamber was flooded with Acetone interference solution during certification.
	interference solution during certification
	()
2.	Visual Inspection
3.	Troubleshooting/Repair
	Return to NDAS for repair + cleaning.
4.	VOC (attached) N/A
5.	Internal Standard value $\leq 3.00\%$ Yes \square No \square N/A
6.	Verify software version
	Return to Factory for Repair
	Ready For Calibration
	Ready For Certification