

In Field Instrument Review 5/30/2016-7/18/2016

100345- AST Soldotna

4/19 RFI- No Action Taken

100346- Fairbanks Airport

1/2 Pump Error- No Action Taken

100347-Cordova PD

1/4 Pump Error-No Action Taken

100349- Ketchikan PD

1/11 RFI-No Action Taken

100354- Bristol Bay Borough PD

3/7 Standard Out of Range- Sent new tank

100355- Seward PD

8/39 RFI- No Action Taken

100357- St. Paul PD

1/2 Blank Error- Blank error after 0.318 subject test. Next blow subject blew 0.316 and had no blank error- No Action Taken

100358- UAA PD

1/2 tank interference and 1/2 Standard Out of Range- Sending an Airgas tank.

100364- APD Jail

1/111 Pump Error, 3/111 Interference, 2/111 Blank Error- No Action Taken

100365- North Pole PD

1/8 Pump Error Status Message- No Action Taken

100370- Homer PD

2/20 Interference, 2/20 Gas Flow Error- Interference Same Subject- No Action Taken

100373- AST Nenana

Gas flow error stopped VOC. Last Subject test 5/16/2016 was gas flow error but good vocs between. Agency will run periodic tests to provide more data for evaluation.

100384- Juneau PD 1

2/25 RFI, 1/25 Pump Error- No Action Taken

100387- Fairbanks PD

1/38 RFI- No Action Taken

100389- AST Girdwood

1/7 RFI- No Action Taken

100390-AST Emmonak

1/2 Tank Interference- No Action Taken

100395- APD Jail

Removed from Service for 5-way valve issue 7/8/2016

100397- King Cove

Removed from Service to troubleshoot modem line.

100400-Palmer PD

8/42 RFI, 5/42 Gas Flow Error- Replace instrument to replace regulator

100403- Denali NP

1/2 RFI- No Action Taken

100404- APD Jail

1/24 Ambient Fail- No Action Taken

100413- AST Cooper Landing

1/9 RFI- No Action Taken

100422- JBER

1/35 RFI, 1/35 Ambient Fail, 2/35 Internal Standard Error 1/35 Detector Overflow- All but RFI on 7/4/2016 and all test types were test- No Action taken

100424- Eielson AFB

1/3 Pump Error- No Action Taken

100667- AST/Matsu West

1/12 RFI- No Action Taken

100668- AST/Bethel

Removed from service for sample chamber temp failure on 7/18 VOC.

100671- AST-Fairbanks

1/28 RFI, 1/28 Pump Error- No Action Taken

100678- AST/Anchor Point

1/7 Internal Standard Error-Appears to be a random spike in internal standard value- No Action taken.

100684- AST/Delta

1/3 RFI-No Action taken

100689- Kotzebue PD

2/24 Tank Interference- No Action Taken

100692- AST/Aniak

1/3 Blank Error- Following a maximum attempts exceeded with a valid test after of 0.238- No Action Taken

100693-Skagway PD

1/9 Pump Error, 1/9 Blank Error, 1/9 Standard Out of Range, 1/9 Internal Standard Error- Instrument removed from service 7/21/2016

100694- Petersburg PD

1/4 Pump Error- No Action Taken

100695- Wasilla PD

2/48 RFI- No Action Taken

100700- Soldotna PD

1/18 RFI- No Action Taken



