

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Effective: 11/10/2021

Version: 2.0

Date: 11/10/2021 Instrument #: 100361

Instrument Location: Anchorage PD

Supervisor Name and Agency: Carlie Glaister SCDL & Daniel Manasco APD

Describe the Status Change or Issue with the Instrument:
During IFIR there were status messages for Diagnostic Failed, which occurred due to low breath tube temperature. On 11/10/2021 I corresponded with Daniel Manasco about this instrument and status message. I inquired about the environment (any fans in room, or unusually cold in room). Manasco informed me that there did not seem to be an unusual draft or blowing on the instrument. Manasco also informed me that after the instrument gave warnings of breath tube not to temperature he restarted the DataMaster, unplugged and plugged back in the breath tube, completed a diagnostic check, and ran a test breath test on 11/6/2021.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: NA

Out of Service Date/Time: NA

For Use by SCDL	Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740