

In Field Instrument Review for 01/03/2016 VOC Day

Date span (12/12/2015 – 01/03/2016)

Performed by Colleen O'Bryant

100344 – AST/Girdwood – No action taken

- RFI(1) 1/3 tests

100345 – AST/Soldotna – No action taken

- RFI(2) 2/5 tests

100349 – Ketchikan PD – New ILMO Installed 1/1/16 by agency

- Standard Out of Range (2) – Low PSI ~300psi

100364 – APD – New ILMO Installed 12/27/2015 by agency

- Tank Interference (5), Blank Error (2) – 77 tests total

100370 – Homer PD – No action taken

- RFI (2) 2/9 tests

100378 – Hooper Bay – Instrument removed from service

- Internal Standard error (1) – multiple occurred following 01/03/2016.

100384 – Juneau PD - New ILMO Installed 12/15/2015 by agency

- Standard Out of Range (1) 1/5 tests.

100395 – APD – No action taken

- RFI (1), Pump Error (1)

100397 – King Cove PD – Monitoring instrument while in service

- Standard Out of Range (2) 2/3 Tests

100398 – Seward PD – No action taken

- RFI (2) 2/4 tests, conducted as a “test”

100402 – Anchorage Airport PD – No action taken

- Standard Out of Range (1), 1/7 tests – followed by a completed test and status message has not been repeated

100404 – Anchorage PD – No action taken

- Blank error (1), Gas flow error (1), 2/14 tests – both followed by a complete test and status message has not been repeated.

100421 – JBER – No action taken

- Pump error (1), 1/10 tests – followed by a complete test and status message has not been repeated.

100678 – AST/Anchor Point – No action taken

- Pump error (1), 1/4 tests - followed by a complete test and status message has not been repeated.

100688 – AST/Soldotna – Instrument removed from service for damage by prisoner

- RFI (2), Tank Interference (1), Standard out of Range (1)

100689 – Kotzebue PD – No action taken

- Tank Interference (5), 5/9 tests – all 5 occurrences of the status message were on the same subject and occurred due to filter 3 exceeding maximum allowable range. Filter readings declined to well within range on future tests.

100690 – Sitka PD – No action taken

- Tank Interference (1), 1/6 tests - followed by a complete test and status message has not been repeated.

100695 – Wasilla PD – No action taken

- RFI (1), 1/14 tests

100697 – Mat-Su West – No action taken

- RFI (2), 2/11 tests – both tests on the same subject and were followed by a completed tests, status message has not been repeated.

100698 – Haines PD – Instrument removed from service interference detected on external standard on 01/03/2016 VOC attempts

- Gas flow error (2), ambient fail (1)

*This data does not include tests run on 100682 (Kake PD) for the duration of 12/12/2015 – 01/03/2016 because the instrument would not upload. Previous in field instrument review did not indicate any status messages during previous time period (10/24/2015 – 12/12/2015).

