

## Alaska Scientific Crime Detection Laboratory

## DataMaster Calibration Form

Issued: 01/27/2012  
Effective: 01/27/2012Version: DMCAF2012 R0  
Status: ActiveInstrument # 100674Date: 5/16/13

## Reason for Calibration

When dmt was turned on the following error was received:  
"An unexpected error occurred in dmt.exe" SI Board was  
replaced at direction of SMCUPAS) and calibration required.

## 1. Wet Bath Simulator Solution

- a. Level 0.100
- b. Manufacturer Guth
- c. Lot 11220
- d. Expiration Date 10/24/13

## 2. Wet Bath Simulator

- a. Serial Number SD1176
- b. Date Calibrated 10/09/12

## 3. Attach Calibration Factors

CALIBRATION FACTORS

-----  
Alaska Department of Public Safety  
DATAMASTER dmt: 100674  
-----

Date: 05/16/2013  
Time: 07:20:44

OPERATOR NAME:  
COLLEEN S OBRYANT  
CERTIFICATE #: 6237

Ca = 0.1000  
CAL = 0.978600    0.800 <= CAL < 1.200  
b1 = 0.0015    0.0000 <= b1 < 0.0040  
b2 = 0.0055    0.0010 <= b2 < 0.0100  
b3 = 0.0006    0.0000 <= b3 < 0.0040  
Xq = 0.1049    0.0500 <= Xq < 0.2000  
a21 = 1.116940    1.050 <= a21 < 1.300  
a31 = 0.416219    0.300 <= a31 < 0.800

Final page for report

\

\ANCSCLSAN01\JTRAX\CASEDOCS\B-100674\B-100674 ECF-20131

11/19/2013