Alaska Scientific Crime Detection Laboratory Change in Instrument Status Form

Version: 6.0

Effective: 1/17/2024

## Date: 3<del>/7/2022</del> 2024.03.07 COB 2024.03.18

Instrument #: 100358

Instrument Location: AST/Mat-Su West

Supervisor Name and Agency: Trooper Barela

Describe the Status Change or Issue with the Instrument:

I contacted Trooper Barela regarding an increase in RFI status messages at the AST/Mat-Su West Post.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: N/A

Out of Service Date/Time: N/A

For Use by SCDL

Additional Notes

Click or tap here to enter text.

## Email completed form to <u>dps.scdl.toxicology@alaska.gov</u>.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor

## **O'Bryant, Colleen S (DPS)**

From:O'Bryant, Colleen S (DPS)Sent:Thursday, March 7, 2024 10:37 AMTo:Barela, Mariano D (DPS)Subject:RE: AST/MSW - RFI Status Messages

I know your DMT location is in the squad room so it's easy for officers to walk through the area. A friendly reminder to turn off radios can alleviate the need to retest subjects. Thanks for getting back with me.

**Colleen O'Bryant** 

Forensic Scientist III - Chemistry Alaska Scientific Crime Detection Laboratory 4805 Dr. Martin Luther King Jr. Ave Anchorage, Alaska 99507

907-269-5783 (direct) 907-350-2111 (cell)

From: Barela, Mariano D (DPS) <mariano.barela@alaska.gov>
Sent: Thursday, March 7, 2024 10:35 AM
To: O'Bryant, Colleen S (DPS) <colleen.obryant@alaska.gov>
Subject: Re: AST/MSW - RFI Status Messages

I asked Olsen about it. He believes his radio was still on. I've tried to recreate the bodycams interfering with the instrument and out of the 5/6 times I couldn't. I've talked to the troopers in the past about this, they think it's the bodyworn cameras causing it but I believe it's forgetting to turn off radios or other troopers walking through with radios on.

Sent from my iPhone

On Mar 7, 2024, at 8:44 AM, O'Bryant, Colleen S (DPS) < <u>colleen.obryant@alaska.gov</u>> wrote:

## Mariano,

This last two months there have been 5/20 RFIs during subject testing. Any thoughts on if this is a training issue with officers (Morris X2, Phillips, Olson X 2) or an environmental issue? Roughly 10% status messages during subject testing can be expected and this is 25%.

5	Serial Number	Test Date	Location			OperatorLastName	SubjectAlcohol_1	Status
1(	00358	1/5/2024 2:44 PM	AST Mat-Su West	4		KLINGEN		Maximum Attempts Exceeded
1(	00358	1/6/2024 8:25 PM	AST Mat-Su West		••	VENABLE	0.00000000	
1(	00358	1/10/2024 9:29	AST Mat-Su West			OLSONGUZMAN	0.4000000	
1(	00358	1/13/2024 1:57	AST Mat-Su West		(	WEBB	0.00000000	
1(	00358	1/18/2024 3:34	AST Mat-Su West	(		MORRIS		RFI
1(	00358	1/18/2024 3:37	AST Mat-Su West	ſ		MORRIS		RFI
1(	00358	1/18/2024 3:39	AST Mat-Su West	ſ		MORRIS	0.18900000	
1(	00358	1/22/2024 4:55	AST Mat-Su West			PHILLIPS		RFI
1(	00358	1/27/2024 8:49	AST Mat-Su West	"		HARRIS	0.23000000	
1(	00358	1/30/2024 11:13	AST Mat-Su West	I		ANDERSON	0.11500000	
1(	00358	2/7/2024 7:06 AM	AST Mat-Su West	1	ŀ	CHRISTNER	0.17100000	
1(	00358	2/13/2024 3:55	AST Mat-Su West	I		BAIRETT		
1(	00358	2/13/2024 4:06	AST Mat-Su West	I		BAIRETT	0.00000000	
1(	00358	2/18/2024 9:23	AST Mat-Su West	1		OLSON		RFI
1(	00358	2/18/2024 9:29	AST Mat-Su West	1		OLSON		RFI
1(	00358	2/18/2024 9:32	AST Mat-Su West	1		OLSON		Maximum Attempts Exceeded
<u>۲</u>	00358	2/18/2024 9:38	AST Mat-Su West	1		OLSON		Maximum Attempts Exceeded
1(	00358	2/18/2024 9:49	AST Mat-Su West	1		OLSON		Pump Error
1(	00358	2/18/2024 9:51	AST Mat-Su West			OLSON	0.22300000	
1(	00358	2/18/2024 10:17	AST Mat-Su West	1	t	HARRIS	0.11700000	

**Colleen O'Bryant** 

Forensic Scientist III - Chemistry Alaska Scientific Crime Detection Laboratory 4805 Dr. Martin Luther King Jr. Ave Anchorage, Alaska 99507

907-269-5783 (direct) 907-350-2111 (cell)