

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 6/11/2014
Effective: 6/11/2014

Version: CIISF 2014 R0
Status: Active

Date: 7-16-15 Instrument Serial Number: B100697

Instrument Location: JAIL

Supervisor Name and Agency: PATRICK E MARTIN / APD

Describe the Status Change or Issue with the Instrument:

Simulator Timed Out

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 7-16-15 / 0738

For Use by SCDL

Additional Notes

Multiple simulator timed out status messages.
Possible controller board issue. 08/16/15

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740