

Alaska Scientific Crime Detection Laboratory

DataMaster Check In Form

Issued: 1/13/2017
Effective: 1/17/2017

Version: DMCIF 2017 R0
Status: Active

Instrument S/N 100402

Received From Intoximeters

Date 09/15/21

Analyst Dereen Walton

1. Reason for instrument return:

Refurbished by manufacturer, repaired for fatal errors

2. Change instrument and case location in JusticeTrax Breath Alcohol Database

3. Ensure change in instrument status form is in JusticeTrax

4. Upload

NA Instrument was not in the field jmw 09/15/21

5. Update agency information and polling status in DM Host Calling Program

6. Check for VOCs

From Intoximeters

7. Intoximeters Repair Paperwork (attached)

SRO Number: SRO-047140

Received Date: 07/26/2021

Completion Date: 08/12/2021

SRO Type: REPAIR

SRO Description: DMT Repair/Preventative Maintenance

Customer ID: C000003651

Customer PO: 07262021-Lee

Contact: Tatiana Lee

Email: tatiana.lee@alaska.gov

Ship To:

Alaska Department of Public Safety
Procurement & Supply Section
4805 Dr. MLK Jr. Avenue
Anchorage AK 99507

Units on SRO

1	LEGDMT	LEGACY DMT
---	--------	------------

Service Line: 1		**All Instruments are Calibrated to Factory Specifications**
Unit Type:	(LEGDMT) LEGACY DMT	
Serial Number:	50100402	
Reason:	DMT Functional	
	Lock Up	
Reason Notes:	Customer Reported Issue: Locks Up or Freezes, Wont Save Test Results	
Resolution:	Adjusted	
	Mech adj	
Resolution Notes:	Added 1/16" spacer between touch screen and front panel	

Parts:	<u>Qty</u>	<u>Part Number</u>	<u>Part Description</u>
	1	59-0097-00	DMT HRDW SHIM WASHER SMALL 30487
Reason:	Preventive Maintenance		
	planned		
Reason Notes:	90-8000-00 Prev Maint Contract		
Resolution:	Prev M		
	planned		
Resolution Notes:	90-8000-00 Prev Maint Contract p/n Installed new BT o ring Tightened rear panel mount connectors Installed TB-30 modifications to the control board. SI green board B1 battery voltage checked = 3.28vdc Replaced standard slotted screws on the SC with torx screws Installed metal seal tape around the SC mirror blocks Cleaned and adjusted the 5-way valve. Cleaned, lubricated, & adjusted filter wheel moving parts Adjusted the air volume: 3.01 Adjusted tech screen settings Adjusted RFI sensitivity Tested modem line pick up Time and date verified. Dry Gas leak checked Parts: (1) 59-0097-00 Shim Washer small (1) 001199-00 3.3V regulator Calibration solution (0.100) Lot# 21080 Bottle# 618 Dry gas: AG106803, Tank 001, Exp. 09-Mar-2023		
	1	001199-00	DMT ELEC REGULATOR V LDO 3.3V OUT 30V IN
	1	90-8000-00	CONTRACT PREV MAINT DMT

Order Packing Slip Report

Intoximeters
Experience · Service · Integrity

8/18/2021 9:54:38 AM

Packing Slip: 234771

Pack Date: 8/18/2021

SRO: SRO-047140



From: Intoximeters, Inc
2081 Craig Road
St Louis MO 63146
USA

Customer: C000003651

Ship To: 2

Alaska Department of Public Safety
4805 Dr MLK Jr Ave
Anchorage AK 99507
USA

Alaska Department of Public Safety
Procurement & Supply Section
4805 Dr. MLK Jr. Avenue
Anchorage AK 99507
USA

Customer PO: 07262021-Lee

Ship Via: FDX

FED EX

Weight: 38.00

Delivery Terms : GND

Shipping Terms : ORIGIN

Packages: 1

Customer Ship Account :

Line Number	Item	UM	Ordered Quantity	Shipment Quantity	Backorder Quantity
1	LEGDMT	LEGACY DMT			50100402
1	59-0097-00	EA		1.00	0.00
	DMT HRDW SHIM WASHER SMALL 30487				
2	001199-00	EA		1.00	0.00
	DMT ELEC REGULATOR V LDO 3.3V OUT 30V IN				
3	90-8000-00	EA		1.00	0.00
	CONTRACT PREV MAINT DMT				

Rec'd 8/20/21
JMV