

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 4/8/21 Instrument Serial Number: ~~100591~~^{S.B.} 100375
Instrument Location: Sharkey Annex, mile 2 Denali Park Road
Supervisor Name and Agency: Shelby Barbay, Denali

Describe the Status Change or Issue with the Instrument: S.B.

~~New unit in service.~~
Putting previous unit back in service.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 1619 hrs 4/8/21

In
DJW 04/09/2021

For Use by SCDL

Additional Notes

Previous instrument 100375 (due for preventive maintenance) was returned to service temporarily due to a screen issue with replacement instrument 100691. 100375 will be replaced later in April, 2021 when an agency representative is able to pick up a Datamaster from Anchorage.

DJW 04/09/2021

Email completed form to dps.scdl,toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740