

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 4.0

Effective: 8/10/2022

Date: 3/24/2023

Instrument #: 100669

Instrument Location: Soldotna AST

Supervisor Name and Agency: Joseph Miller AST

Describe the Status Change or Issue with the Instrument:

Instrument was taken out of service and replaced due to continued touch screen issues. Essentially the screen is non-responsive to touch. Instrument exhibiting no status messages and with the exception of the touch screen was working without issue. VOC ran and passed prior to out of service action. Instrument will be sent back to SCDL.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: [Click or tap here to enter text.](#)

Out of Service Date/Time: 03/24/2023 at 2035 hours

For Use by SCDL

Additional Notes

[Click or tap here to enter text.](#)

Email completed form to dps.scdl.toxicology@alaska.gov
For questions contact the Breath Alcohol Program at 907-269-5740

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor