

Alaska Scientific Crime Detection Laboratory

DataMaster Check In Form

Effective: 10/10/2022

Version: 3.0

Instrument #: 100387

Received From: Intox

Date: 10/23/23

Analyst: Carlie Glaister

Reason for instrument return:

Returned from Intox. Was sent due to filter wheel status messages.

Change instrument and case location in JusticeTrax Breath Alcohol Database

~~Ensure change in instrument status form is in JusticeTrax~~ See 100387 2023.06.19 Repair for Return to Factory info

~~Upload~~ No agency info to upload. Modem did connect CWB 10/23/23

CWB 10/23/23

Update agency information and polling status in DMHost Calling Program

~~Check for VOCs~~ CWB 10/23/23
No agency VOCs to check.

From Intoximeters

Intoximeters Repair Paperwork (attached)

SRO Number: SRO-057720

Received Date: 07/05/2023

Completion Date: 09/11/2023

SRO Type: REPAIR

SRO Description: DMT Repair

Customer ID: C000003651

Customer PO: 07052023-OBryant

Contact: Colleen OBryant

Email: Colleen.obryant@alaska.gov

Ship To:

Alaska Scientific Crime Detection Laboratory
4805 Dr MLK Jr Ave
Anchorage AK 99507
USA

Units on SRO

1	LEGDMT	LEGACY DMT
---	--------	------------

Service Line: 1		**All Instruments are Calibrated to Factory Specifications**	
Unit Type:	(LEGDMT) LEGACY DMT		
Serial Number:	50100387		
Reason:	DMT Status Messages		
	FitWl er		
Reason Notes:	Customer Reported Issue: Filter wheel issue		
Resolution:	Replaced		
	RPL comp		
Resolution Notes:	Replaced locking solenoid and optical positions sensor. Rebuilt filter wheel assembly and cleaned optics. Inspected and adjusted to factory specs.		
Parts:	<u>Qty</u>	<u>Part Number</u>	<u>Part Description</u>
	1	59-0080-00	DMT ELEC ASSY SOLENOID FILTR WHEEL 41344
	2	59-0079-00	DMT ELEC ASSY OPTICAL FILTER 41467