Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 6/11/2014 Version: CIISF 2014 R0 Effective: 6/11/2014 Status: Active Date: 3-3-15 Instrument Serial Number: 100 673 Instrument Location: Delta Junction Supervisor Name and Agency: Trp- Colley, Malvin Describe the Status Change or Issue with the Instrument: Takin out of Service due to purp many corres. If instrument was placed in service or removed from service, fill out the appropriate sections below. In Service Date/Time: Out of Service Date/Time: 3-3-15 @ 1550 Additional Notes For Use by SCDL internal, standard errors along with

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740