

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 5-19-2020 Instrument Serial Number: B-100689

Instrument Location: North Processing Room

Supervisor Name and Agency: P.E MARTIN / APD

Describe the Status Change or Issue with the Instrument:

DMT placed "Out of Service" by Officer D. SITZ due to an internal standard status message followed by a filter wheel 2 won't zero status message.
It also failed the diagnostic check on a VOC.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 5-18-2020

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740