

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 5/29/20 Instrument Serial Number: 100350

Instrument Location: VALDEZ, ALASKA

Supervisor Name and Agency: SGT. CHAD CLEMENTS VALDEZ POLICE DEPT.

Describe the Status Change or Issue with the Instrument:

The instrument is having multiple issues. I coordinated with the lab on some things I could do to try and resolve the issue.
The instrument is having issues above my skill level.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 5/29/20 1630

For Use by SCDL

Additional Notes

Multiple instances of detector overflow DJW 05/29/2020

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740