

# Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 6/11/2014  
Effective: 6/11/2014

Version: CIISF 2014 R0  
Status: Active

Date: April 15, 2016 Instrument Serial Number: 100398

Instrument Location: Seward Police Department 410 Adams St, Seward AK 99664

Supervisor Name and Agency: Armstrong Seward PD

Describe the Status Change or Issue with the Instrument:

Taking instrument out of service and sending to the crime lab for service at their request.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: \_\_\_\_\_

Out of Service Date/Time: April 15, 2016 2315 hours

For Use by SCDL

Additional Notes

*Eddie Armstrong reported the black O-ring was missing from the DMT regulator as well as the view tank, he attempted to install possibly cross-threaded. CDS 4/18/16*

Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)

For questions contact the Breath Alcohol Program at 907-269-5740

## **O'Bryant, Colleen S (DPS)**

---

**From:** O'Bryant, Colleen S (DPS)  
**Sent:** Monday, April 04, 2016 9:30 AM  
**To:** Eddie Armstrong (earmstrong@cityofseward.net)  
**Cc:** brandi.barnett@alaska.gov; Foster, Charles R (DPS); Roth-Frey, Nicolette A (DPS)  
**Subject:** RE: Seward ILMO

Eddie,

**Since the plastic O-ring for the regulator has come off we are going to take this opportunity to check over the instrument and regulator. We'll ship you a new instrument this week.**

**Please fill out a change in instrument status form for your current instrument taking it out of service.**

Colleen

**From:** DPS SCDL Toxicology (DPS sponsored)  
**Sent:** Monday, April 04, 2016 7:05 AM  
**To:** O'Bryant, Colleen S (DPS); Foster, Charles R (DPS); Barnett, Brandi M (DPS)  
**Subject:** FW: Seward ILMO

---

**From:** Eddie Armstrong [earmstrong@cityofseward.net]  
**Sent:** Sunday, April 03, 2016 6:56 AM  
**To:** DPS SCDL Toxicology (DPS sponsored)  
**Cc:** Doreen Valadez (Seward PD); Allen Nickell (Seward PD)  
**Subject:** Seward ILMO

Toxicology,

I attempted to change out the ILMO bottle in Seward with the last one sent to us, LOT # 01315080A3. The newer bottle will not thread into the datamaster and the small black plastic O-ring that goes over that threaded receiver is broken. Can we get a new ILMO and an O-ring and I will replace them both?

Thank you,

Eddie Armstrong