

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 6/11/2014
Effective: 6/11/2014

Version: CIISF 2014 R0
Status: Active

Date: 11/25/15 Instrument Serial Number: 100353

Instrument Location: North Pole PD

Supervisor Name and Agency: Jed Smith NPPD

Describe the Status Change or Issue with the Instrument:

Taking unit out of service. Unit's screen has failed.
VOC not possible.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 11/25/15 1715

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740