Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017 Effective: 12/15/2017

Version: CIISF 2017 R0

Status: Active

Date: 8/1/19 Instrument Serial Number: 100354
Instrument Location: DECLINGHAM
Supervisor Name and Agency: TANEK LOWERY DILLINGTAM PD
Describe the Status Change or Issue with the Instrument:
INSTRUMENT WOLD NOT ALL RECEIVER WHEN SUBJECT BLOWS
If instrument was placed in service or removed from service, fill out the appropriate sections below.
In Service Date/Time:
Out of Service Date/Time: 8/1/19 6:18pm
For Use by SCDL Additional Notes

 $\begin{tabular}{ll} Email completed form to $\underline{\tt dps.scdl.toxicology@alaska.gov}$ \\ \end{tabular}$

For questions contact the Breath Alcohol Program at 907-269-5740