

Alaska Scientific Crime Detection Laboratory

DataMaster Check In Form

Effective: 10/10/2022

Version: 3.0

Instrument #: 100398

Received From: Intoximeters

Date: 2/20/24

Analyst: Carlie Glaister

Reason for instrument return:

Filter wheel errors, possibly damaged regulator.
Repaired by manufacturer.

- Change instrument and case location in JusticeTrax Breath Alcohol Database
- Ensure change in instrument status form is in JusticeTrax N/A, not placed in/out of service
- Upload N/A, not removed from service
- Update agency information and polling status in DMHost Calling Program N/A, already correct in DMHost
- Check for VOCs N/A, not removed from service

From Intoximeters

Intoximeters Repair Paperwork (attached)

* No keyboard returned w/ instrument.

SRO Number: SRO-060458

Received Date: 01/17/2024

Completion Date: 01/22/2024

SRO Type: REPAIR

SRO Description: DMT Repair

Customer ID: C000003651

Customer PO: 01172024-OBryant

Contact: Colleen OBryant

Email: Colleen.obryant@alaska.gov

Ship To:

Alaska Scientific Crime Detection Laboratory
4805 Dr MLK Jr Ave
Anchorage AK 99507
USA

Units on SRO

1	LEGDMT	LEGACY DMT
---	--------	------------

Service Line: 1		**All Instruments are Calibrated to Factory Specifications**	
Unit Type:	(LEGDMT) LEGACY DMT		
Serial Number:	50100398		
Reason:	DMT Status Messages		
Reason Notes:	FltWl er		
Resolution:	Replaced		
Resolution Notes:	RPL comp		
Reason:	Preventive Maintenance		
Reason Notes:	planned		
Resolution:	Replaced		
Resolution Notes:	Replaced solenoid Rebuilt filter wheel assembly Performed filter wheel test= 30:0		
Reason:	Preventive Maintenance		
Reason Notes:	Phoenix connector terminal mechanical failure, no latch.		
Resolution:	Replaced		
Resolution Notes:	RPL mech		
Reason:	Preventive Maintenance		
Reason Notes:	planned		
Resolution:	Adjusted		
Resolution Notes:	Performed inspection and adjusted instrument to factory specifications.		
	1	001199-00	DMT ELEC REGULATOR V LDO 3.3V OUT 30V IN
Reason:	Preventive Maintenance		
Reason Notes:	Preventative Maintenance		
Resolution:	Adjusted		
Resolution Notes:	Elec adj		
	1	59-0132-00	DMT ELEC SCREW TERMINAL 7 POS 28528
Reason:	Preventive Maintenance		
Reason Notes:	planned		
Resolution:	Update		
Resolution Notes:	DMTVR3		
	1	59-0080-00	DMT ELEC ASSY SOLENOID FILTR WHEEL 41344
Reason:	Preventive Maintenance		
Reason Notes:	TB-30 mod not present		
Resolution:	Update		
Resolution Notes:	Performed TB-30 mod @ control board.		

Order Packing Slip Report

Intoximeters
Experience · Service · Integrity

1/30/2024 7:59:11 AM

Packing Slip: 299450

Pack Date: 1/30/2024

SRO: SRO-060458



From: Intoximeters, Inc
2081 Craig Road
St Louis MO 63146
USA

Customer: C000003651

Ship To: 1

Alaska Department of Public Safety
4805 Dr MLK Jr Ave
Anchorage AK 99507
USA

Alaska Scientific Crime Detection
Laboratory
4805 Dr MLK Jr Ave
Anchorage AK 99507
USA

Customer PO: 01172024-OBryant

Ship Via: FDX

FED EX

Weight: 38.00

Delivery Terms : 2D

Shipping Terms : ORIGIN

Packages: 1

Customer Ship Account :

Line Number	Item	UM	Ordered Quantity	Shipment Quantity	Backorder Quantity
1	LEGDMT	LEGACY DMT			50100398
1	001199-00	EA		1.00	0.00
	DMT ELEC REGULATOR V LDO 3.3V OUT 30V IN				
2	59-0132-00	EA		1.00	0.00
	DMT ELEC SCREW TERMINAL 7 POS 28528				
3	59-0080-00	EA		1.00	0.00
	DMT ELEC ASSY SOLENOID FILTR WHEEL 41344				