Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Effective: 11/10/2021		Version: 2.0
Date: 5/6/2022	Instrument #: 10040	02
Instrument Location: AST/	Tok	
Supervisor Name and Ager	ncy: Carlie Glaister - SCDL	
Describe the Status Chang	e or Issue with the Instrument:	
previously observed that the pressure tank. However, the Breath Test Supervisor Cody he next month to collect m	nitored due to Standard Out of Range external standard was trending lose external standard appears normally Webb requesting him to perform a ore data for review.	ow on subject tests with a high I on VOCs. An email was sent to a once weekly breath test over
	n service or removed from service,	
In Service Date/Time: <u>NA</u>		
	NA	
For Use by SCDL		

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740