Alaska Scientific Crime Detection Laboratory

DataMaster Check In Form

Issued: 7/10/2015
Effective: 7/10/2015

Instrument S/N | 100351 | Received From | NPAS |

Date | 7/30|15 | Analyst | Branch | Barne | 7 |

1. Reason for instrument return: | Pas | For lapar |

2. Change instrument and case location in JusticeTrax Breath Alcohol Database | 2 |

3. Ensure change in instrument status form is in JusticeTrax | 1/A |

4. Upload | 1/2 | A |

5. Update agency information and polling status in DM Host Calling Program | 2 |

6. Check for VOCs | 1/4 |

1. Received From | NPAS | Received From | NPAS |

From NPAS

7. NPAS Repair Paperwork (attached)

Packing List

From: National Patent Analytical Systems Inc. 2090 Harrington Mem. Rd., Mansfield, Ohio 44903

Cust No. ak6056a Sales Order No. 49665 Ord Date 6/18/15

Ship Date 7/14/15 Packing List No. 74289

Cust Purch Ord No. COLLEEN

Ship To:

Bill To:

Alaska Dept of Public Safety

Scientific Crime Detection

Alaska Dept of Public Safety

Scientific Crime Detection

25.00

4805 Dr. Martin Luther King Dr.

4805 Dr Martin Luther King Dr.

.

Anchorage

Ak 99507

Anchorage

Ak 99507

Freight

Attn:

Ship Via FedEx

Comments Service for 100351

Part / Drawing No / Rev No	Quantity Ordered	This Shipment	Back Total Ship Ordered To Date	Description	NP Invent Ref
No Draw # / NONE	1.0	1	1.0	DATAMASTER DMT SERVICE RETURN	ODIET
100351 Serial Nos					9DMT
No Draw # / NONE	1.0	1	1.0	NANUK CASE	NOTE
Serial Nos.					NOTE
No Draw # / NONE	1.0	7	1.0	Service Charge for Repair	2500
Serial Nos.					R500-1
No Draw # / NONE	1.0	1	1.0	Service Charge for Repair, Additional	
Serial Nos.					R500-2

••	19 665 5/18/15		National Patent Analytical Systems, Inc. Service Action Report					
Customer	Alaska Dept of P	ublic Phone 90	07-269-5582	Contact Bolz				
War Exp 1	/13/13	Мх Ехр	Ship Damage	? OY ON	Cust Pick Up?? ○ Y ● N			
shipping dan	ents: note any nage or estimates ng with accessori							
-	blem seen and/or nents received	gas flow error	· · · · · · · · · · · · · · · · · · ·					
Keyword		·						
Finding		Error Code	Enter	Hours 2.0				
Performed	nents and work		s. Reads low on Ga set voltages, calib		ftware, purged system, tandard tests ok			
Solution Lo	t No 15040							
	Lamp 1.790	et Values In Brth Vol 1.44	and the second second	Set Values Out Brth Vol	1.510			
	Meter 0.395				0.333			
	Stability 0.001		Stability 0.0	•	{O.333			
Part No	Qty Pick	Back Total Ordered ship	Laccrintion		Price Ea			
9DMT	1.0		DATAMASTER DMT	SERVICE RETURN				
NOTE	1.0	100	NANUK CASE	elizanem	****			
INOIE		:	NANUK CASE					
R500-1	1.0		Service Charge for Repair 0.000					
R500-2	1.0		Service Charge for I	Repair, Additiona	al Hours 0.000			
	to the state of th				they a below the second			