Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017 Effective: 12/15/2017 Version: CIISF 2017 R0 Status: Active

Date: 03/15/2018	Instrument Serial Number: 100684
Instrument Location: [Delta AST
Supervisor Name and	Agency: Malik Jones / Alaska State Troopers
	nange or Issue with the Instrument: io was in the vicinity but powered off.
Standard Out of Range	
Internal Standard Error	
Taken Out of Service	
Check O-Ring where the dry	gas cylinder screws on, it was leaking.
If instrument was place In Service Date/Time:	ed in service or removed from service, fill out the appropriate sections below.
Out of Service Date/Ti	ime: _03/01/2018 at 1101 hours.
For Use by SCDL	Additional Notes
- + 	
	Email completed form to <u>dps.scdl.toxicology@alaska.gov</u>
For	r questions contact the Breath Alcohol Program at 907-269-5740

Page 1 of 1 All printed copies are uncontrolled. Approved by Forensic Alcohol Supervisor