

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 6.0

Effective: 1/17/2024

Date: ~~10/24/2025~~ **10/24/2025 DJW 10/24/2025**

Instrument #: 100687

Instrument Location: Squad Room **King Cove PD DJW 10/31/2025**

Supervisor Name and Agency: Chris Babcock

Describe the Status Change or Issue with the Instrument:

Internal Standard Error

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: Click or tap here to enter text. Out

of Service Date/Time: 10/24/2025 1500

For Use by SCDL

Additional Notes

Click or tap here to enter text.

Email completed form to dps.scdl.toxicology@alaska.gov.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor