

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 1/4/2013
Effective: 1/4/2013

Version: CIISF2013 R0
Status: Active

Date: June 22, 2015 Instrument Serial Number: 100371

Instrument Location: Glacier Bay NP&P

Supervisor Name and Agency: Wendy Bredow - Glacier Bay NP&P - National Park Service

Describe the Status Change or Issue with the Instrument:

The DMT was placed in "In-Service" status. This instrument replaces DMT #100691

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: June 22, 2015, approx. 1508

Out of Service Date/Time: _____

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740