

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 6.0

Effective: 1/17/2024

Date: 3/11/26

Instrument #: 100390

Instrument Location: Juneau

Supervisor Name and Agency: Salisbury / JPD

Describe the Status Change or Issue with the Instrument:

Filter Wheel Error

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time:

Out of Service Date/Time: 3/11/26 1602 hours

For Use by SCDL

Additional Notes

Instrument 100390 removed from service at Juneau PD on 3/11/2026 due to persistent filter wheel errors. CKG 3/13/2026

Email completed form to dps.scdl.toxicology@alaska.gov.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor