

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Effective: 11/10/2021

Version: 2.0

Date: 11/22/2021 Instrument #: 100361

Instrument Location: Anchorage PD

Supervisor Name and Agency: Carlisle Claster SCDL

Describe the Status Change or Issue with the Instrument:
Instrument was removed from service due to breath
nose being unable to reach minimum temperature.
Failure OIG 11/22/21

Received an email from Daniel Manasco on 11/13/2021
notifying the lab that the instrument was removed from
service.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 11/13/2021

For Use by SCDL	Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740