

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 6/11/2014
Effective: 6/11/2014

Version: CIISF 2014 R0
Status: Active

Date: 16 Feb 17 Instrument Serial Number: B-100420

Instrument Location: Fort

Supervisor Name and Agency: Shannon Gustafson / Fort Greely PD

Describe the Status Change or Issue with the Instrument:

Machine reads external cylinder as empty (2 times)

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: NA

Out of Service Date/Time: 16 Feb 17 / 1350

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740