

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Effective: 11/10/2021

Version: 2.0

Date: 6/10/22 Instrument #: SN: 100683

Instrument Location: Glennallen

Supervisor Name and Agency: Tra Somerville AST

Describe the Status Change or Issue with the Instrument:

The screen stopped responding to a stylus or touch.
I tried calibrating stylus and power cycling.
The issue started intermittent then stopped responding completely
over 2 weeks.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 6/11/22 1000

For Use by SCDL

Additional Notes

DUC FOR PREVENTATIVE MAINTENANCE ON 06/21/22.

TAL 06/17/22

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740