

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 5-11-18 Instrument Serial Number: 100678

Instrument Location: Anchor Point AST

Supervisor Name and Agency: Romy Simon / AST

Describe the Status Change or Issue with the Instrument:

Instrument keeps locking up.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: ~~5-11-18 / 11:30~~ 3/25/2018 JMY 07/24/18

For Use by SCDL

Additional Notes

External standard expired 3/25/2018. No tank change evident. Instrument out of service after tank expiration. Instrument replaced 5/11/2018. JMY 07/24/18

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740